



## Sole Adhesion Tester

The tester is used to determine the peeling strength between sole and upper of finished shoe.

Cutter's width

20±0.1 mm or 10±0.05 mm

Cutter's moving down speed 20±2 mm/min

Elevating range 40 mm

Display method U20 indicator

Dimension (WxDxH) 60 x 40 x 85 cm

Weight 45 kg

Power 1  $\phi$  , AC220V 50Hz

